

LISTING OF BUILDING WITH ASBESTOS CONTAINING CEILING AND/OR WALL MATERIAL

Date: February 20, 2015

2' X 4' Ceiling Tiles				
Building Name	Room Numbers	Type of Ceiling	Type of Asbestos	Percent of Asbestos
Med Wing F	Basement	(2' X 4')	Chrysotile	2-5%
Med Wing B	108	(2' X 4')	Chrysotile	2%
Mitchell Hall	7, 105, 105A, 107, 107A, 107B, 108, 110, 113A, 113, 114, 115, 119, 120, 121, 121A, 2 nd floor hallway referred to as Room 200	(2'X4')	Amosite	4-10%
Swain Hall	100A, 102, 103, 106, 130G, 230J, 221	(2' X4')	Amosite and Chrysotile	1-5%
Dey Hall	1 st floor hallway, 115, 100B, 2 nd floor hallway, 200C, 2 rd floor hallway, 300C, 327, 341, 4 th floor hallway, 442, 440, 438, 443, 441, 439, 422, 420, 418, 423, 421, 400B	(2' X 4')	Amosite and Chrysotile	1-5%
Hickerson House	200, 201, 211, 204, 208, 205, 206, hallway	(2' X 4')	Chrysotile	2%
Vance Hall	Room 124	(2' X4')	Chrysotile	2%
Davie Hall	338, 338A, 338B, 329	(2' X 4')	Chrysotile	2%

LISTING OF BUILDING WITH ASBESTOS CONTAINING CEILING AND/OR WALL MATERIAL

Date: February 20, 2015

Building Name	Room Numbers	Type of Ceiling Tile	Type of Asbestos	Percent of Asbestos
Alumni Hall	101, 101C, 101B, 101A, 103, 106, 106A, 107, 107A, 107B, 100A, 108A, 108B, 108, 109, 109A, 109B, 111, 204, 204A, 204B, 204C, 209, 209A, 209B, 211, 211A, 211B, 201, 201A, 201B, 201C, 202A, 202B, 202, 301, 301A, 302, 303A, 303B, 303C, 303D, 304, 305, 305A, 305B, 305C, 305D, 306, 306A, 306B, 307, 310, 311, 312, 313, 313A, 313B, 401, 401A, 401B, 401C, 403, 405, 406, 407, 408, 409A, 409B, 409C, 409D, 413, 413A, 413B, 413C, 414	(2' X 4')	Chrysotile	2%
12" Spline Ceiling Tiles				
Hill Hall	Various Locations	12" spline tiles	Amosite	10-15%
Old Clinic	Various Locations	12" spline tiles	Amosite and Chrysotile	1-5% 4%
Manning Hall	Various Locations	12" spline tiles	Chrysotile	2-5%
Phillips Hall	Basement walls-Rooms 20, 29	12" spline tiles	Chrysotile	2%
Note: There may be additional buildings with spline ceiling systems that contain asbestos. A complete inspection has not been performed in buildings that included spline ceiling systems.				
Soundproofing Peg Board				

Swain Hall	Various Locations	Soundproofing Peg Board	Chrysotile	40-55%

LISTING OF BUILDING WITH ASBESTOS CONTAINING CEILING AND/OR WALL MATERIAL

Date: August 1, 2011

Building Name	Room Numbers	Type of Ceiling Tile	Type of Asbestos	Percent of Asbestos
Spray-Applied Ceiling Material and Textured Paint Coatings				
Carrington Hall (old section)	Throughout including walls (Removed from the ceiling in Rooms 217, 218, 304, 312 and 03)	Spray-applied ceiling material	Chrysotile	5-10%
Mitchell Hall	Throughout- Exception: Rooms 220 and 221 were abated	Spray-applied ceiling material	Chrysotile	5-10%
Kenan Labs	Throughout-Exception: 1 st , 2 nd , 3 rd , 4 th and 5 th floors were abated	Spray-applied ceiling material	Chrysotile	3-5%
Van Hecke Wettach	Various rooms including only those rooms where it is exposed: 3038, 4082, 4085, 5042, 5045, 5048 and 5052	Spray-applied ceiling material	Chrysotile	15-20%
Morrison Residence Hall	Throughout the resident rooms on the walls	Elastomeric coating on the walls	Chrysotile	10%
Hinton James Residence Hall	Throughout and on walls	Spray-applied ceiling material and elastomeric coating on the walls	Chrysotile	10%

Brauer Hall	Overspray coating on top two course of the exterior block walls and in the pits and divots on the concrete ceiling deck	Spray-applied ceiling material	Chrysotile	10-15%
-------------	---	--------------------------------	------------	--------

LISTING OF BUILDING WITH ASBESTOS CONTAINING CEILING AND/OR WALL MATERIAL

Date: February 20, 2015

Building Name	Room Numbers	Type of Ceiling Tile	Type of Asbestos	Percent of Asbestos
Daniels Student Store	Overspray coating on top two course of the exterior block walls and in the pits and divots on the concrete ceiling deck of the 2 nd floor	Spray-applied ceiling material	Chrysotile	5-10%
Alumni Hall	ME Rooms ONLY – All floors-Oversprayed on walls, ceilings, and mechanical system	Spray-applied ceiling	Chrysotile	2-3%
Avery Residence Hall	Throughout the resident rooms and suite hallways	Textured coating on the ceiling	Chrysotile	2-3%
Parker Residence Hall	Throughout the resident rooms and suite hallways	Textured coating on the ceiling	Chrysotile	2-3%
Teague Residence Hall	Throughout the resident rooms and suite hallways	Textured coating on the ceiling	Chrysotile	2-3%

LISTING OF BUILDING WITH ASBESTOS CONTAINING CEILING AND/OR WALL MATERIAL

Date: February 20, 2015

Building Name	Room Numbers	Type of Ceiling	Type of Asbestos	Percent of Asbestos
Spray-Applied FireProofing Material				
Hamilton Hall	Throughout-Exception: Abated in Rooms 100, 150, 351, 420, 423, 425, 452, 470, 517, 519, 523, 570	Spray-applied fireproofing on structural steel above the suspended ceiling system	Chrysotile	15-20%
Morehead Planetarium	Morehead House and Observatory-1 st , 2 nd , 3 rd , & 4 th . The fireproofing was removed in the 2 nd floor banquet hall (Room 106) and Rooms G1-G4	Spray-applied fireproofing on structural steel above a plaster ceiling	Chrysotile	>70%
Plaster Wall and Ceiling Material				
Bowman Gray Pool	Entire pool area	Plaster wall and coating on ceiling beams (skim coat layer)	Chrysotile	6%
Manly Residence Hall	Entire building	Plaster walls and ceilings (brown coat layer)	Chrysotile	<1-2%
Grimes Residence Hall	Entire building	Plaster walls and ceilings (brown coat layer)	Chrysotile	<1-2%
Ruffin Residence Hall	Entire building	Plaster walls and ceilings (brown coat layer)	Chrysotile	<1-2%
Mangum Residence Hall	Entire building	Plaster walls and ceilings (brown coat layer)	Chrysotile	<1-2%

