



Inspection Report

UNIVERSITY OF NORTH CAROLINA

Customer ID: 826

Certificate: 55-R-0004

@ CHAPEL HILL

Site: 001

1100 BIOINFORMATICS BLDG

DIVISION OF LABORATORY ANIMAL MEDICINE

Type: ROUTINE INSPECTION

Date: Jan-27-2010

CHAPEL HILL, NC 27599

3.2 (d)

INDOOR HOUSING FACILITIES.

Interior surfaces. The floors and walls of indoor housing facilities, and any other surfaces in contact with the animals, must be impervious to moisture. The ceilings of indoor housing facilities must be impervious to moisture or be replaceable.

***In one cat room housing approximately a dozen cats, one area of the ceiling is water-damaged and the ceiling board has separated, creating a significant hole. The damaged area is not directly over the cat runs, however, ceilings in animal rooms need to be maintained so that they are impervious to moisture. Need to repair ceiling damage and underlying cause to ensure that the ceiling is impervious to moisture and can be adequately sanitized. Correct by February 28, 2010.

Prepared By:

F MIAVA BINKLEY, DVM USDA, APHIS, Animal Care

Date:

Title: VETERINARY MEDICAL OFFICER Inspector 1020

Jan-28-2010

Received By:

DR. NELSON GARNETT

Date:

Title: INTERIM DIRECTOR

Jan-28-2010