



ROY COOPER
Governor

MICHAEL S. REGAN
Secretary

MICHAEL SCOTT
Director

SENT VIA ELECTRONIC MAIL

September 5, 2017

Eric Nesbit, PE
Geosyntec Consultants of NC, PC
2501 Blue Ridge Road, Suite 430
Raleigh, NC 27607

Re: REC Work-Phase Audit
UNC-Cogeneration Facility
575 West Cameron Avenue
Chapel Hill, Orange County, NC
Site ID No.: NCR000010272

Dear Mr. Nesbit:

As required by law, the Inactive Hazardous Sites Branch (Branch) performs audits of remedial actions carried out by environmental consulting firms at sites in the privatized Registered Environmental Consultant (REC) Program. Self-certification by RECs replaces state oversight of the cleanup activities. As such, auditing of remedial activities for regulatory compliance is conducted to ensure protection of public health and the environment and to evaluate progress toward achieving cleanup goals. These audits also help us improve our procedures, guidance documents, and training for RECs working on projects in the program.

I have reviewed the following documents describing the remediation activities at the UNC-Cogeneration Facility site and certified by you as the Registered Site Manager (RSM):

- Remedial Investigation Work Plan – October 2013
- Remedial Investigation Report – May 2016

My review did not reveal any deficiencies or potential REC Rule violations. The Branch appreciates the remedial efforts performed at the Site by the University of North Carolina at Chapel Hill and Geosyntec Consultants of NC, PC. If you have any questions or would like a paper copy of this letter mailed to you, please contact me at (919) 707-8349 or Janet.Macdonald@ncdenr.gov.

Sincerely,

Janet K. Macdonald, P.G.
Hydrogeologist
REC Program

Cc: Mary Beth Koza, Director, Environment, Health and Safety, UNC Chapel Hill